

Honeywell Announces Obsolescence of its ASG Pressure Sensors, Last Time Buy

September 18, 2018

Due to the obsolescence of existing ASG Pressure Sensor starting material and the phase out of processing equipment, effective immediately, Honeywell Sensing and Internet of Things (SIoT) will no longer support its ASG Sensors (part numbers listed below). Honeywell values its customers and realizes that transitioning from ASG sensors to the Honeywell replacement sensor may require transition time. Accordingly, Honeywell is willing to facilitate a Last Time Buy for customers to help ease that transition.

Please place your last order by Dec 7, 2018 as no orders will be accepted after this date. This provides our customers with a 90-day period to analyze upcoming demand requirements and place an order. Honeywell reserves the right to review last time buy orders to determine if they can be filled. Due to significant changes in supply chain and production activities, changes may apply to Minimum Order Quantities (MOQ) and/or Product Price.

Affected Series and Part Numbers

This announcement will serve as the formal communication that the SKUs listed below will no longer be available for sale in accordance with the Timeline of Events (shown below). Replacement part numbers (where available) are provided in Annex 1 below.

Product Name	SERIES	Part Number
SCC		SCC05GSMT, SCC100ASMT, SCC15ASMT, SCC15ASMTT, SCC15GSMT, SCC30ASMT, SCCP05GSMT, SCCP05GSMT-ZSEN, SCCP05GSMTTP, SCCP100ASMT, SCCP100ASMT-ZSEN, SCCP100GSMT, SCCP100GSMTTP, SCCP15ASMTLP, SCCP15ASMTTP, SCCP15GSMTTP, SCCP30GSMTTP
CPC		CPC0.3GFH, CPC01GFC, CPC100AFH, CPC100GC, CPC100GFC, CPC100GFH, CPC150AFH, CPC15AC, CPC30DFC, CPC60GFH, CPCL04DC, CPXL04GF, CPXL10GF
CPX		CPXL04GF, CPXL10GF
DUX		DUXL01D
SCDA		SCDA102-XPC01GTH, SCDA120-XSC05DC, SCDA121 CPCL04GFC=, SCDA124 XCX15ANH, SCDA135 XPC15ATC, SCDA138 DCXL01DS, SCDA139 DCXL05DS, SCDA140 DCXL30DS, SCDA141 XPCL04DTC, SCDA142 XPCL10DTC, SCDA143 XPCL10DH
SXP		SXP100GSMTTP, SXP01GSMTTP, SXP100ASMTTP, SXP100GSMTTP, SXP150ASMT, SXP150ASMTTP, SXP15ASMTTP, SXP30ASMTTP
SZ		SZ76167 SCXL004DN
SX		SX15ASMT, SX01GSMT, SX100ASMT, SX100GSMT, SX100GSMT-JB, SX150ASMT, SX15ASMT, SX15GSMT, SX15GSMT-JB, SX30ASMT, SX30GSMT

Timeline of events

The following timeline pertains to all retired SKUs listed in the table above. These dates are subject to change based on component availability.

- Last Time Buy - Honeywell will not accept orders after this date - December 7, 2018
- Last Time Ship - Honeywell will not ship products after this date - December 31, 2018

Regions affected

- Asia Pacific (APAC)
- Europe, Middle East, Africa (EMEA)
- Greater China (GrCH)
- Latin America (LATAM)
- North America (NA)

Annex 1

RETIRED PART NUMBER	POSSIBLE REPLACEMENT PART NUMBERS
SCCP05GSMT	TBPDANS005PGUCV
SCCP05GSMT-ZSEN	TBPDANS005PGUCV
SX30GSMT	TSCSNBN030PGUCV
CPC0.3GFH	SSCSANN010NGAA5
CPC01GFC	SSCDANN001PGAA3
CPC100AFH	SSCSANN100PAAA5
CPC100GC	SSCSANN100PAAA6
CPC100GFC	SSCSANN100PAAA7
CPC100GFH	SSCSANN100PAAA8
CPC150AFH	TSCSANN150PGUCV
CPC15AC	SSCSNNN015PAAA5
CPC30DFC	SSCSANN030PAAA5
CPC60GFH	TSCSANN060PGUCV
CPCL04DC	TSCSAAN060PDUCV
CPXL04GF	TSCSANN060PGUCV
CPXL10GF	SSCSANN010NGAA5
DUXL01D	NSCSDRN001NDUNV
SCC05GSMT	NBPDLNN005PGUNV
SCC100ASMT	NBPDANN100PAUNV
SCC15ASMT	NBPDLNN015PAUNV
SCC15ASMTT	NBPLLNN015PAUNV
SCC15GSMT	NSCDANN015PGUNV
SCC30ASMT	NSCDANN030PAUNV
SCCP05GSMTTP	NSCDANN005PGUNV
SCCP100ASMT	NSCDRRN100PAUNV
SCCP100ASMT-ZSEN	NSCDRRN100PAUNV
SCCP100GSMT	TSCDLNN100PGUCV
SCCP100GSMTTP	TSCDLNN100PGUCV
SCCP15ASMTLP	NSCDRNN015PAUNV
SCCP15ASMTTP	NSCDRNN015PAUNV
SCCP15GSMTTP	NSCDANN015PGUNV
SCCP30GSMTTP	NSCDRRN030PGUNV
SCDA102-XPC01GTH	NSCSAAN010NGUNV
SCDA120-XSC05DC	NSCSAAN010NGUNV
SCDA121 CPCL04GFC=	NSCSAAN010NGUNV
SCDA124 XCX15ANH	NSCSANN004NGUNV
SCDA135 XPC15ATC	NSCSANN010NGUNV
SCDA138 DCXL01DS	NSCSDRN001NDUNV
SCDA139 DCXL05DS	NSCSAAN010NGUNV
SCDA140 DCXL30DS	NSCSAAN010NGUNV

SCDA141 XPCL04DTC	NSCSAAN010NGUNV
SCDA142 XPCL10DTC	NSCSAAN010NGUNV
SCDA143 XPCL10DH	NSCSAAN010NGUNV
SX01GSMT	NSCDLNN001PGUNV
SX100ASMT	NSCSANN100MGUNV
SX100GSMT	NSCSANN100MGUNV
SX100GSMT-JB	NSCSANN100MGUNV
SX150ASMT	NBPD PNS150PAUNV
SX15ASMT	NBPD LNN015PAUNV
SX15ASMT	NBPDANS015PGUNV
SX15GSMT	NBPDANS015PGUNV
SX15GSMT-JB	NBPDANS015PGUNV
SX30ASMT	NBPLPNN030PAUNV
SXP01GSMT	NBPD PNS001PGUNV
SXP100ASMT	NBPLPNN100PAUNV
SXP100GSMT	NBPDANN100PGUNV
SXP100GSMT	NBPDANN100PGUNV
SXP150ASMT	NBPD PNS150PAUNV
SXP150ASMT	NBPD PNS150PAUNV
SXP15ASMT	NBPLPNN015PAUNV
SXP30ASMT	NBPDANN030PAUNV
SZ76167 SCXL004DN	no replacement

Contact information

If you have questions, please contact your Honeywell Sales Consultant, Honeywell Sales Representative, or Regional Product Manager.

- North America: Clinton Briscoe, Product Marketing Manager, clinton.briscoe@honeywell.com, +763.954.4189
- EMEA: Simon Anderson, Product Specialist, simon.anderson@honeywell.com, +44 1698 481104
- Greater China: Jeffrey Zhang, Product Marketing Specialist, liqing.zhang@honeywell.com, +862180387423
- APAC: Jeevesh Bawa, Product Marketing Manager, jeevesh.bawa@Honeywell.com, +912066039400

Resources

- [Affected part numbers](#)
- [Customer letter](#)
- [Product obsolescence notice](#)

Warranty / Remedy

Honeywell warrants goods of its manufacture as being free of defective materials and faulty workmanship during the applicable warranty period. Honeywell's standard product warranty applies unless agreed to otherwise by Honeywell in writing; please refer to your order acknowledgement or consult your local sales office for specific warranty details. If warranted goods are returned to Honeywell during the period of coverage, Honeywell will repair or replace, at its option, without charge those items that Honeywell, in its sole discretion, finds defective. If Honeywell is unable to repair or replace the goods, it will provide a credit for the impacted goods. The foregoing is buyer's sole remedy and is in lieu of all other warranties, expressed or implied, including those of merchantability and fitness for a particular purpose. In no event shall Honeywell be liable for consequential