



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000873

DATE: 24-Aug-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	73M1902-IVT/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1902-IVTR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1912-IVT/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73M1912-IVTR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1113F-CGT/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1113F-GTR/F/P2	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1121F-CGVR/F1	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1210F-68IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1210F-68IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1210F-68M/F/PB	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1210F-68M/F/PH	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S1210F-68M/F/PJ	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8009C-32IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8009C-32IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8009CN-32IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8009CN-32IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8010C-IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8010C-IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8010R-IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8010R-IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8023C-IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8023C-IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8024RN-20IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8024RN-20IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8024RN-IM/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	73S8024RN-IMR/F	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 24-Sep-2018

Discontinuance	MAX3681EAG+	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured
Discontinuance	MAX3681EAG+T	N/A	24-Aug-2019	23-Feb-2020	Part can no longer be manufactured